FIELD INSPECTION REPORT

Date of Inspection: 02/12 District: 2020 PATNA Division: DANAPUR Length (km): 3.0 Rd to must fatur. Name of the Road: Repair of Rd foom fainal to Sadisopus Scheme/Programme: **MAINTENANCE** Package No.: Road Id No .: Status of the Project: Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance Work is a case of: Sl. No. Parameters to be checked Remarks Pavement Road Junction condition SAL b) Condition of Surfacing S/Uc) Riding Quality S/Ud) Road Camber SAJ Whether free from defects such as visible cracks, exposed e) Yes/No aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) Yes/No Compaction of flank/slope & raincuts if any g) Yes/No-2. Cross Drainage With the company of the control of the control of the control of Condition of head walls in Hume pipe culverts including its painting a) 8/SRI/4 Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/IL Condition of railings/slab/approach for Bridges c) S/SPI/IJ Road Furniture 3. Whether sign boards/informatory/cautionary Board/km & 200m a) Yes/No stones/Pavement road markings are provided and maintained Compliance History Status of ATR's & any others a)

Overall Rating

Satisfactory (S)	•
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

2/120 J-E, Bilta

02/12/20

(Signature)

NAME: Anil

Anil Kumas

DESIGNATION: J.E. Bihta