

FIELD INSPECTION REPORT

Date of Inspection : 02.12.20		District: Gaya	
Division : Gaya		Length (km): 4.10 K.M.	
Name of the Road: Gaya Nawada N.H. to Gaya Pachpur S.H.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained		200m ✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar
NAME:

Harishankar
(Signature) 02.12.20
I.E.