FIELD INSPECTION REPORT

Date of Inspection: 2.12.2020 Division: GAYA			District: GAYA Length (km): 4.00 kt/l	
Scheme/Programme: MAINTENANC Package No.: Status of the Project: Ongoing/Comple		MAINTENANCE	MAINTENANCE - 3054 (o(d)) Road Id No.: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		Up gradation/ Maintenance		
Sl. No.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Parameters t	o be checked	Remarks
1,	Pavement			
a)	Road Junction condition			s/U
b)	Condition of Surfacing			√s/U
c)	Riding Quality			√\$/U
d)	Road Camber			V S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yeshio)
f)	Contraction Joints provided or not (CC Pavement)			Yes/No

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Compliance History Status of ATR's & any others a)

Condition of railings/slab/approach for Bridges

Compaction of flank/slope & raincuts if any

Cross Drainage

Road Furniture

5 Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No

NO

NAME: Chandrashelder Kamer

DESIGNATION: TE

g)

2.

a)

b)

c)

3.

a)

4.

Overall Rating