FIELD INSPECTION REPORT

		FIELD INSTE	CHON REPORT	
Date of I	nspection: O	3-11-2020	District: Lakhisara	<u> </u>
Division			Length (km): 5.215 K	1. Via Dak
Name of	the Road: L	akhisarai Sh	eikhlura Rd to Garsano	rs ···
Scheme/	Programme:	MAINTENANCE		
Package	No.:		Road Id No.:	
Status of the Project: Ongo		Ongoing/Completed	I/Under Maintenance Jp gradation/ Maintenance	
Work is a case of:		New Connectivity/C	of graduations	Remarks
Sl. No.	Phrameters to be checked			
1.	Pavement			SAU
a)	Road Junction condition			ŞAU
b)	Condition of Surfacing			ŞAU
c)	Riding Quality			SH
d)	- 10 har			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No Yes/No
f)	Contraction Joints provided or not (CC Pavement)			
g)	Contraction Joints provided of not (Compaction of flank/slope & raincuts if any Yes/No			Yes/No
ž.,	Cross Drainage			
. Valleton	Condition of head walls in Hume pipe culverts including its painting			
<u>a)</u>	Condition of Head Walls in France p.p. Condition of Abutment & Wing walls, Slab in RCC culverts S/S			,s/sri/U
b)	Condition of Abutment & Wing Wans, Olde in Condition of railings/slab/approach for Bridges			S/SRI/U
c)	Condition of railings/saovapprouch to Engle			
3.	Road Furnitu		Visit Co. Co. Co.	
a)	stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NO

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	•

(Signature)

NAME:
