FIELD INSPECTION REPORT

		<u>FIELD INSPE</u>	CTION REPORT		
D 461"	amostion · 2	-12-2020	District: Supaul		
Date of Inspection: 2-12-2020 District: Supaul Division: Birpus Length (km): 0.600 Name of the Road: Repair of Road from Lureigent Gantalgan; to Manufell And INTENANCE				ti partela	
Division:	ha Boad: 12	Cabair of Road for	rom Luxuigarh Ganpatganj to Mi	isti Pitte	
Name of	rogramme:	MAINTENANCE			
Package			Road Id No.: 2100500805	2	٠
Package of	the Project:	Ongoing/Complete	d/Under Maintenance		
	a case of:	New Connectivity/	Up gradation/ Maintenance		1
SI. No.	J. Zillia Butali	Parameters to		Remarks	
MALONE VIS. 12	iz.			State with the	
		Sold All Control	$f_{i,j}^{(i)} = g_{i,j}^{(i)} = g_{i,j}^{(i)$	√\$/U	1
a)	Road Junction	n condition		S/U~	1
b)	Condition of	Condition of Surfacing			S/U \/ \8/U
c)	Riding Quality Road Camber				
				√8/U	
d)	Whether fre	e from defects su	ch as visible cracks, exposed	Yes/No No	-applicable Not-applicable
e)	aggregates in case of CC Pavement.			Yes/No	Not-applicable
~ f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any Yes/No			Y es/No	
1. 14 5 Year 1/15	Cross Drain	or consistent of the second of		aria kayund	
2	Cluss Diam	Shood walls in Hume I	nine culverts including its painting	s/ski/u	
a)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
b) -	Condition of Abutment & wing wans, Side in Telegraph for Bridges		✓S/SRI/U		
c)	Condition of railings/slab/approach for Bridges				
3.	Road Furni	ture			
a)	Whether sig	gn boards/informator ment road markings a	ry/cautionary Board/km & 200m re provided and maintained	Yes/No	
TEFS AND S	Compliance	e History			l i
4: a)	Status of AT	ΓR's & any others		Not Region	1 4

Overall Rating :

Satisfactory (S)	_=
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: ARSUN PRASAD.

DESIGNATION: EE, RWD, WOLLS DIVINON
BILLING

Scanned by CamScanner