

# FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District: Katihar
Division : Barsoi		Length (km): 7.280
Name of the Road: Dakaitpuja to Maheshpur		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21105608039
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*(Signature)*

NAME: SANJAY KUMAR ROY

DESIGNATION: E.E  
RIID, Barsoi