

FIELD INSPECTION REPORT

Date of Inspection: 02-12-20		District: - Kishanganj	
Division: - Kishanganj-I		Length(km): 2.50 KM	
Name of the Road: Repair of road from Mahadev Dighi to Bishampur road			
Scheme/Programme:		MAINTENANCE	
Package No.: - N/A		Road Id No.: 21205808071	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	
Sl. No	<u>Parameters to be checked</u>	Remarks	
1.	Pavement	S/U	
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	S/U ✓	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N/A	Yes/No	
f)	Contraction Joints Provided or not (CC Pavement) N/A	Yes/No	
g)	Compaction of flanks/ slopes & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR pending	

Overall Rating :

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	U

NAME: E. Arun Prakash.

Clear
 2/12/20
 (Signature)
 Executive Engineer
 R.W.D. Works Division
 Kishanganj-1