

## FIELD INSPECTION REPORT


<b>Date of Inspection:</b> - 02-12-20		<b>District:</b> - Kishanganj	
<b>Division:</b> - Kishanganj-1		<b>Length(km):</b> - 6.70 KM	
<b>Name of the Road:</b> - Tulsiga TO LRP via Gangwan road			
<b>Scheme/Programme:</b>		MAINTENANCE	
<b>Package No.:</b> N/A		<b>Road Id No.:</b> 21205808072	
<b>Status of the Project:</b>		Ongoing/Completed /Under Maintenance ✓	
<b>Work is a case of:</b>		New Connectivity/ Up gradation / Maintenance ✓	

Sl. No	<u>Parameters to be checked</u>	Remarks
1.	<b>Pavement</b>	S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N/A	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement) - N/A	Yes/No
g)	Compaction of flanks/ shop & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	ATR Not pending

**Overall Rating :**

<b>Satisfactory(S)</b>	-
<b>Satisfactory but requires Improvement (SRI)</b>	-
<b>Unsatisfactory(U)</b>	U

  
 (Signature)

**NAME:** Eo. Radheshyam prajapati  
 J.E, R.W.D (W) Div. Kishanganj-1