

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Kishanganj	
Division : Kishanganj - 2		Length (km): 2.100 Kms	
Name of the Road: Repair of Road from Tedagachh to Balubadi Via Matiyari Part 'A'			
Scheme/Programme: MAINTENANCE		Road Id No.: 21205908042	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U U (Flood Affected)	
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes	
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes	
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	Yes/No Yes	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 02/12/2020

NAME: Ramanand Yadav.

Signature: Junior Egg
Digital Bank