

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Kishanganj
Division : Kishanganj-2	Length (km): 4.00 Km
Name of the Road: Repair of Road from Taiyabpur to Dalua Haat	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 21205908050
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A. Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	N.A. Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	N.A.
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature) AE

NAME:

DESIGNATION: