

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Kishanganj	
Division : Kishanganj-2	Length (km): 5.800 KM	
Name of the Road: Repairs of road from Kharadahi to Basta Kola Bhokarduari		
Scheme/Programme: MAINTENANCE MR/3054	Road Id No.: 21205908054	
Package No.:		
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	Yes/No ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✗ Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Bishan Mandal
JE/Thakurgar

Acup
02/12/2020
(Signature)
Biswanath
02/12/2020
JE