

FIELD INSPECTION REPORT

Date of Inspection :		District: - Gtarnad	
Division: Beland		Length (km): 6.75 km	
Name of the Road: Repair of Road from Gtarnad to Pachauri Road			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓SU	
b)	Condition of Surfacing	✓SU	
c)	Riding Quality	✓SU	
d)	Road Camber	✓SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓SSRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓SSRI/U	
c)	Condition of railings/slab/approach for Bridges	✓SSRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	✓	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

Sukumar

(Signature)

NAME: Sukumar Kumar

DESIGNATION: Assistant Engineer