

FIELD INSPECTION REPORT

Date of Inspection :		District: Sitamarhi
Division : Belharah		Length (km): 5.60 km
Name of the Road: Repair of Road from Patahi to Panchapur Road		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	LSU
b)	Condition of Surfacing	LSU
c)	Riding Quality	LSU
d)	Road Camber	LSU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	LS/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	LS/SRI/U
c)	Condition of railings/slab/approach for Bridges	LS/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	X

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	✓

S. Kumar

(Signature)

NAME: - Sushil Kumar

DESIGNATION: - Assistant Engineer