FIELD INSPECTION REPORT

		A A Designation of the last of			
•		10020	District: East Champena	M	
Date	of Inspection: \(\lambda \)	1124	Length (km): /2.0 Km		
Divisi	ion: Azera	14 Sansramber	to Avery Val Barry Larly	(Parts	
Name	of the Road: 5H	MAINTENANCE	Road Id No.: 31702308	-	
Schen	ne/Programmo.			30.63	
Beake	ge No.:	Ongoing/Complete	ed/Under Maintenance		
Status	of the Project.	New Connectivity	Up grauators		
	is a case of:	New York			
SL No					
	Pavement			S S/U	
	Road Junction	condition	-	< \$/ U	
a)					
b)	Condition of Surfacing			S S/U	
c)	Riding Quality			S S/U	
d)	Road Camber	- 	h on visible cracks, exposed	No Yes/No	
$\overline{}$	Whether free	from defects st	nch as visible cracks, exposed	Notari	
e)	aggregates in ca	ise of CC Pavellic	16.	XeYes/No	
f) .	Contraction Join	nts provided or not	(CC Pavement)	1-1	
-/	Compaction of flank/slope & raincuts if any NeYes/No				
g)	Compaction of Hallostope & Fallow				
1	F. MINITED			C PROLE	
	三中小时间 Carlo	ed wells in Hume	pipe culverts including its painting	S S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting				
b) `	Condition of Abutment & Wing walls, Slab in RCC culverts				
<u> </u>	Condition of railings/slab/approach for Bridges				
c)		是是"是"的"			
				IAZ	
	syd Alexandra	hoards/informato	y/cautionary Board/km & 200r	n Yes Yes N	
) [Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
- 1					
的結構	Compliance				
	1			No	
8	Status of ATR's	& any others		1.0	

Overall Rating

Satisfactory (S)	the later tops
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Alygro

NAME: Asholofal

DESIGNATION: TE