

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	East Champaran
Division :	Raxaul	Length (km):	5.0 Km
Name of the Road:	Repair of road from Bhabhi to Kaurada		
Scheme/Programme:	MAJNET PLANET	3054	
Package No.:	14	Road Id No.:	317008502090
Status of the Project:	Ongoing	Completed/Under Maintenance	
Work is a case of:	New Connectivity/Upgradation	Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/C
b)	Condition of Surfacing	✓ S/C
c)	Riding Quality	✓ S/C
d)	Road Camber	✓ S/C
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Blank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/P/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/P/U
c)	Condition of railings/slab/approach for Bridges	✓ S/P/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (L)	

Handwritten Signature
2/12/20
(Signature)

NAME: Mr. Hitesh Kumar Singh

DESIGNATION: Junior Engineer, Raxaul