

# FIELD INSPECTION REPORT

Date of Inspection:	03/12/2020	District:	Duarbhangga
Division:	Duarbhangga	Length(Km):	3.3
Name of Road:	Kangwa Gumti NH 57 to Ranipur Nandal choudhary tota		
Scheme/Programme:	Maintenance		
Package No.	m2.3054/	Road Id No.	31909208157
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <b>NO</b>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <b>yes</b>
g)	Compaction of flank /slope & raincuts if any	Yes/No <b>NO</b>
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	N/A S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U <b>N/A</b>
<b>3</b>	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No <b>NO</b>
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	<b>No.</b>

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<b>U</b>

Partially road length at different point is damaged due to current year flood.

Name:  
Designation:

S

03/12/2020  
S/E

R

3/12/20  
AE

(Signature)

R