

# FIELD INSPECTION REPORT

Date of Inspection:	3/12/2020	District:	Barbhangha
Division:	Barbhangha	Length(Km):	3.8
Name of Road:	NH 57 to Kangsi Jalwar		
Scheme/Programme:	Maintenance		
Package No.	MR-3054	Road Id No.	31903208158
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
<b>1</b>	<b>Pavement</b>		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <sup>yes</sup>	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <sup>yes</sup>	
g)	Compaction of flank /slope & raincuts if any	Yes/No <sup>yes</sup>	
<b>2</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <sup>N/A</sup>	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U <sup>N/A</sup>	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U <sup>N/A</sup>	
<b>3</b>	<b>Road Furniture</b>		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No <sup>yes</sup>	
<b>3</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others	NO.	
Overall Rating:			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

Partially road length is damaged due to one year flood. As road submerges till month.

Name:

Designation:

3/12/2020  
J.E.

3/12/2020  
J.E.

(Signature)  
3-12-2020  
J.E.