

# FIELD INSPECTION REPORT

|                                      |                                            |
|--------------------------------------|--------------------------------------------|
| Date of Inspection : 3/12/2020       | District: Madhubani                        |
| Division : Madhubani                 | Length (km): 13.00                         |
| Name of the Road: Ijara to Sallaikha |                                            |
| Scheme/Programme:                    | MAINTENANCE                                |
| Package No.:                         | Road Id No.: 31909608100                   |
| Status of the Project:               | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                   | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | S/U S       |
| b)      | Condition of Surfacing                                                                                               | S/U S       |
| c)      | Riding Quality                                                                                                       | S/U S       |
| d)      | Road Camber                                                                                                          | S/U S       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No Yes  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Yes  |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U SRI |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U SRI |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U SRI |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No No   |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others <i>Surface on three reaches damaged during flood '20.</i>                               | No ATR      |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | —   |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          | —   |

*[Signature]*  
(Signature) 3/12/20

NAME: Navesh Kumar  
DESIGNATION: A.E., Rahika

*[Signature]*  
J.E., Rahika  
(Paramath Sah)