

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020 District: Madhubani
 Division: RWD, Araria Div. Benipatti Length (km):
 Name of the Road: Dhaktari to Akaur
 Scheme/Programme: MAINTENANCE

Package No.: NA Road Id No: 31910008043
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Ruling Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of U.C. Pavement	Yes ✓
f)	Contraction Joints provided or not in U.C. Pavement	✓
g)	Connection of flank slope & raincuts if any	✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	✓ SRI
c)	Condition of railings Slab approach for Bridges	✓ SRI
3.	Road Furniture	
a)	Whether sign boards informative cautionary Board km & stones Pavement road markings are provided and maintained	Yes ✓
4.	Compliance History	
a)	Score of ATR & all others	Not any

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

02-12-2020

(Signature)

NAME: Md. Sami

DESIGNATION: J.E, RWD, Benipatti
 Section: Benipatti