FIELD INSPECTION REPORT

		2/12/2000		
Date of Inspection:			District: Palme	
Division: Patra			Length (km): 2.90KM	
Name of the		atchpur	Brahmabthan to	Bhaisl
Scheme/Prog		MAINTENANCE	D - LLINo.	
Package No.: MR - N 70B-20 Pata Re			Koad Id No.:	aintanu
Status of the Project: Ongoing/Completed Work is a case of: New Connectivity/		Many Connectivity/	/Under Maintenance (New Maintance	
Sl. No. Paran				
1. Pa	Pavement			
a) Ro	Road Junction condition			S/U
b) Co	Condition of Surfacing			S/U
c) Ri	Riding Quality			S/U
d) Ro	Road Camber			S/U
e) W	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f) Co	Contraction Joints provided or not (CC Pavement)			Yes/No
g) Co	Compaction of flank/slope & raincuts if any			Yes/No
2. Cr	Cross Drainage - N: A			
a) Co	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) Co	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c) Co	Condition of railings/slab/approach for Bridges			S/SRI/U
3. Ro	Road Furniture - N.A			
W	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4. Co	Compliance History - NO			
a) Sta	Status of ATR's & any others			
	nork is yet to Start.			
Overall Rati	ing :	Satisfactory (S)		
			requires Improvement (SRI)	
		Unsatisfactory (U) •	

(Signature)2/12/2000

NAME: Pra-Fall Chandra Prabhal.

DESIGNATION: A .E