

# FIELD INSPECTION REPORT

Date of Inspection :		03.12.2020		District :		MUNGER	
Division :		Khatagola - Tapani		Length (Km) :		5.00 K.M.	
Name of the Road :		Khatagola Jamai Gangla mukhy path to Landiya Domasi Reth via Landiya nod path					
Scheme/Programme :		MAINTENANCE ✓					
Package No. :				Road Id No. :		20803800534 Project ID-	
Status of the Project :		Ongoing/Completed/Under Maintenance					
Work is a case of :		New Connectivity/Up gradation/Maintenance ✓					
Sl. No.	Parameters to be checked					Remarks	
1	<b>Pavement</b>						
a)	Road Junction condition					✓S/U	
b)	Condition of Surfacing					✓S/U	
c)	Riding Quality					✓S/U	
d)	Road Camber					✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)					✓Yes/No	
g)	Compaction of flank/slope & raincuts if any					✓Yes/No	
2	<b>Cross Drainage</b>						
a)	Condition of head walls in Hume pipe culverts including its painting					✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U	
c)	Condition of railings/slab/approach for Bridges					S/SRI/U	NA.
3	<b>Road Furniture</b>						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained					✓Yes/No	
4	<b>Compliance History</b>						
a)	Status of ATR's & any others					No.	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar  
DESIGNATION : A-E

J. Kumar  
03.12.2020  
(Signature)