

FIELD INSPECTION REPORT

Date of Inspection : 2-12-2020	District: Darbhanga
Division : Darbhanga-1	Length (km): 2.00 km
Name of the Road: Ukharra to Jhakharri Pakar Path	
Scheme/Programme: MAINTENANCE	
Package No.: MR 3054	Road Id No.: 31909200838
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	- Nil -

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Note :- Road damaged in Flood this year temporary restoration work done. Road completely submerged under water till two months.

(Signature) 02/12/2020

NAME: Vinay Kumar

DESIGNATION: Assistant Engineer
R.W.D. (S&J) Subdiv - Bahadurpur/Hanumanagar