

Block:- pispaindi

# FIELD INSPECTION REPORT

Date of Inspection :	2/12/2020	District:	Bhagalpur
Division :	Kahalgauh	Length (km):	9.450 Km
Name of the Road:	payalapur to Sarkanda Jark path		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20703400823
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/K 5
b)	Condition of Surfacing	S/U 3
c)	Riding Quality	S/U 3
d)	Road Camber	S/U 3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No Km Not marked.
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Qm  
2/12/2020

(Signature)

NAME: