


### FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020		District: Gaya	
Division : RWD Imangay		Length (km): 4.5KM.	
Name of the Road: Ban Bazar Imangay to Ludhiga.			
Scheme/Programme: MAINTENANCE			
Package No.: -		Road Id No.: 10502400808	
Status of the Project: Ongoing/Completed Under Maintenance		Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	<b>Pavement</b>		
a)	Road Junction condition		SU 'S'
b)	Condition of Surfacing		SU 'S'
c)	Riding Quality		SU 'S'
d)	Road Camber		SU 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No 'No'
f)	Contraction Joints provided or not (CC Pavement)		Yes/No 'Y'
g)	Compaction of flank/slope & raincuts if any		Yes/No 'Y'
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U 'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U -
c)	Condition of railings/slab/approach for Bridges		S/SRI/U -
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No 'Y'
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		No ATR.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
 (Signature) A.E. 2.12.20

NAME: Nishu K. Singh  
 AE RWD Imangay