

FIELD INSPECTION REPORT

Date of Inspection :	03/11/2020	District:	Lakhsarai
Division :	Lakhsarai	Length (km):	3.28 K.M.
Name of the Road:	Repair of Road from To4 (mananpur) to Nagerdev Yoder Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20804600824
Status of the Project:	Ongoing/Completed/Under Maintenance - Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance - Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/N	
b)	Condition of Surfacing	S/N	
c)	Riding Quality	S/N	
d)	Road Camber	S/N	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

S. M.
03/11/2020
(Signature) A.E.

NAME:

REGISTRATION NO.: