

## FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District :	Muzga
Division :	Wing for Transfer	Length (Km) :	3.50 km
Name of the Road :	Chandpura to Kahwa Road		
Scheme/Programme :	MAINTENANCE MR(3054) old.		
Package No. :		Road Id No. :	20803860843
Status of the Project :	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	—
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	—
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4	Compliance History		
a)	Status of ATR's & any others	No ATR.	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME :

AMRENDRA KUMAR

DESIGNATION : J.E

(Signature)

