FIELD INSPECTION REPORT

Date of Inspection:	02.12.2090	District: Madhuban
Division: Jainag	The second secon	Length (km): L-84 Km.
Name of the Road: p	Prograt to Dhulp	ard via Andharathari Road.
Scheme/Programme:	MAINTENANCE	/
Package No.:	*	Road Id No.: 319097 00811
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks	
-1.	Payement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
- d) ~	Road Camber	√\$/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
- g)	Compaction of flank/slope & raincuts if any	¥Yes/No	
- 2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓s/sri/u	
c)	Condition of railings/slab/approach for Bridges	√S/SRI/U	
-3.	Road Furniture -		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	and the same of th	
a)	Status of ATR's & any others	N0	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: Er. Chandra Kishor sahg

DESIGNATION: 2-8