## FIELD INSPECTION REPORT

	f Inspection:	3-12.20	District: Patry		
Division: Majourh: Length (km):					
	of the Road: 10	EDA TO Barki	Changema		
	Programme:	MAINTENANC	E Did		
Packag			Road Id No.:		
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Un gradation/ Maintenance					
	The state of the s	New Connectivit	y/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			✓ <sub>S/U</sub>	
d)	Road Camber .			∨S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Draining			162/140	
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance Hi			and the same	
a) :	Status of ATR's	& any others		NO	

Overall Rating :

Satisfactory (S)	751
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ajay Kunav Lings
DESIGNATION: ER PUTD Masourhi