FIELD INSPECTION REPORT

Date of	Inspection:		TION REPORT		
Division	n: Masau	3.12.20	District: Patorg		
	f the Road:		Length (km): 12.700		
Scheme	Programme:	SPM Road to			
Packago	c No.:	MAINTENANCE	0 d.		
	of the Project:	Ongoing/Completed	Road Id No.:		
Work is	a case of:	Ongoing/Completed/	Under Maintenance		
Sl. No.	A STATE OF THE PARTY OF THE PAR	The state of the s	p gradation/ Maintenance		
1.	Pavement	Parameters to	oe checked	Remarks	
a)	The state of the s				
76.37	Road Junction condition			SAL A	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			✓ S/U	
d)	Road Camber			✓ S/U	
	· · · · · · · · · · · · · · · · · · ·			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any				
2	Cross Draines	Part of the second		Yes/No	
a)					
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitu			O	
	Whether sign	The state of the s	2		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
24期例	Compliance!			-	
a)	Status of ATR'	s & any others	and other hours, help had a few for the	NO	

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ajay KYMGT Lings

DESIGNATION: ERRND MASAUTHS