

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020.		District : GAYA	
Division : Neemchak Bathani ; Sub Division - Manpur		Length (Km. :	
Scheme/Programme: M/R - 3054	MAINTENANCE	Gaya Sarbahda to Kathautiya Road in Manpur Block	
Package No. : N/A		Road Id No. : N/A	
Status of the Project : Ongoing	Ongoing/Completed/Under Maintenance		
Work is a case of : Maintenance	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Work in Progress	Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes	Yes/No
4	Compliance History		
a)	Status of ATR's & any others. A.T.R. No.-3542, Awarded Grade - RI, Not Regraded yet.		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
A. E. R. W. D.
Manpur.