


FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District : GAYA
Division : Neemchak Bathani ; SubDivision - Manpur		Length (Km. : 2.20 Km.
Scheme/Programme: M/R - 3054	MAINTENANCE	Gaya Nawada to Goga Road (Class II)
Package No. : N/A		Road Id No. : N/A
Status of the Project : Ongoing	Ongoing/Completed/Under Maintenance	
Work is a case of : Maintenance	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1 Pavement		
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes Yes/No
g)	Compaction of flank/slope & raincuts if any	Work in Progress Yes/No
2 Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3 Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No
4 Compliance History		
a)	Status of ATR's & any others. ATR No.- 6145, Awarded Grade-RI, Not Regraded yet.	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 03/12/2020
 A.E. R.W.D.
 Manpur.