

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District : GAYA	
Division : Nemchak Bathani ; Sub Division – Manpur		Length (Km. : 1.90 Km.	
Scheme/Programme: M/R - 3054		MAINTENANCE Gaya Khijar Sarai to Village Jehana Road (Class-II)	
Package No. : N/A		Road Id No. : N/A	
Status of the Project : Ongoing		Ongoing/Completed/Under Maintenance	
Work is a case of : Maintenance		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1 Pavement			
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	work in progress.	Yes/No
2 Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes	Yes/No
4 Compliance History			
a)	Status of ATR's & any others. ATR No-5915, Awarded Grade-R.I. Not Regraded yet.		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Prif
03/12/2020
A.E. R.W.D.
Manpur.