

# FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District :	BHAGALPUR
Division :	NAUGACHIA	Length (km) :	3.500 K.M.
Name of the Road :	R.C.D. ROAD No. 14 LATTIPAKAR CHOK TO DIMHAUSIA VIA ABHIYA BAZAR		
Scheme/Programme :	Maintenance 3054 M/R		
Package No. :		Road Id No. :	20703300814
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameteres to be checked	Remarks	
1	Pavement		
a)	Road Junction conditon	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Road Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads markinga are provided and maintained.	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	N/O	

Overall Rating

Satisfactory (S) ✓

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME : RAMASHISH PRASHAD

DESIGNATION : E.E. NAUGACHIA

(Signature)

Executive Engineer  
R. W. D. W. D., Naugachia

02/12/2020  
J.E