

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: BHAGALPUR
Division : RWD Works Div. Nongachia	Length (km): 8.000 Km
Name of the Road: Sonbassha Dumuki Chowk to NH 31 Bisbanna via Bhagmospur	
Scheme/Programme:	MAINTENANCE
Package No.: MR 3054	Road Id No.: 20203300817
Status of the Project:	Ongoing/Completed/Under Maintenance Ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance up gradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U S
b)	Condition of Surfacing	✓S/U S
c)	Riding Quality	✓S/U S
d)	Road Camber	✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Pras
02/12/2020
J-E

NAME: RAMASHISH PRASAD

DESIGNATION: EXECUTIVE ENGINEER

R. W. D.
(Signature)
Executive Engineer
R. W. D., W. D., Nongachia