

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: East Champaran	
Division : Roxaul		Length (km): 2.60 km	
Name of the Road: Hanoi Adda Station to Dubwa Tola 55B camp			
Scheme/Programme: MAINTENANCE		3059	
Package No.:		Road Id No.: 31708500847	
Status of the Project:		Ongoing/ completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4. Compliance History		
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mithilesh Kumar Singh
 DESIGNATION: Junior Engineer, Roxaul

Mithilesh
 2/12/20
 (Signature)