

# FIELD INSPECTION REPORT

|                        |                                             |              |            |
|------------------------|---------------------------------------------|--------------|------------|
| Date of Inspection :   | 02/12/2020                                  | District:    | Jahangabad |
| Division :             | Jahangabad                                  | Length (km): | 1.20       |
| Name of the Road:      | Hulgaung - makhampur PWD Road to ubel Path. |              |            |
| Scheme/Programme:      | MAINTENANCE                                 |              |            |
| Package No.:           |                                             | Road Id No.: |            |
| Status of the Project: | Ongoing/Completed/Under Maintenance         |              |            |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance  |              |            |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                      |              |
| a)      | Road Junction condition                                                                                              | ✓ S/✓        |
| b)      | Condition of Surfacing                                                                                               | ✓ S/✓        |
| c)      | Riding Quality                                                                                                       | ✓ S/✓        |
| d)      | Road Camber                                                                                                          | ✓ S/✓        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No N.A.  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No N.A.  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No     |
| 2.      | <b>Cross Drainage</b>                                                                                                |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U    |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U N.A. |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N.A. |
| 3.      | <b>Road Furniture</b>                                                                                                |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No     |
| 4.      | <b>Compliance History</b>                                                                                            |              |
| a)      | Status of ATR's & any others                                                                                         |              |

Overall Rating :

|                                             |       |
|---------------------------------------------|-------|
| Satisfactory (S)                            | " S " |
| Satisfactory but requires Improvement (SRI) | X     |
| Unsatisfactory (U)                          | X     |

02.12.2020  
(Signature)

NAME: Naresh Kumar Choudhary  
DESIGNATION: A.E