## FIELD INSPECTION REPORT

	e Road: NH-	MAINTE	le school fachturi Hoov Shyamhagar L NANCE 3054 MR Class - I	Ja raentan
kage No	(A)(0)		Road Id No.:	
			Completed/Under Maintenance	
ork is a	case of:	New Con	nectivity/Up gradation/ Maintenance	
Sl. No. Paramete		Part	ameters to be checked	Remarks
1.	Pavement			
n)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Win		nt & Wing walls, Slab in RCC culverts	S/SRI/U
c)	- U. Ciliaus/slab/approach for Bridges		/slab/approach for Bridges	S/SRI/U
3.	Road Fur	niture		
a) Whether stones/Pa		sign boards/informatory/cautionary Board/km & 200m vement road markings are provided and maintained		n Yes/No
4. Compliance		ce History		-
a) Status of ATR'		ATR's & 1	any others	NIL
0	-Il Pating	: =		
Overall Rating :		S	atisfactory (S)	2
		S	atisfactory but requires Improvement (SRI)	

(Signature) J. E

NAME: Around Ruman

DESIGNATION: JUNIOR ENGINEER