

# FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Nalanda
Division : Bihar Sahi	Length (km): 7.90 KM
Name of the Road: NH82 Soyba TO Masixg Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓ S
b)	Condition of Surfacing	S/U ✓ S
c)	Riding Quality	S/U ✓ S
d)	Road Camber	S/U ✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓ NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓ NA
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓ NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓ NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓ NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-NO-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Nimesh Yadav

DESIGNATION: J.E