FIELD INSPECTION REPORT

| | f Inspection : | 3.12.20 | District: Patng | |
|---|--|---------------------------------|--|-------------------------|
| Division: Maseurshi | | | Length (km): O.650 | |
| | | | resorau to Medni Bighs | |
| | e/Programme: | MAINTENANCE | 3054 OLA | |
| Package No.: | | 10 100 | Road Id No.: | |
| | of the Project: | | Up gradation/ Maintenance | |
| AND DESCRIPTION OF THE PERSONS ASSESSMENT | s a case of: | Parameters to | | Remarks |
| Sl. No. | Alle Alexander | and the second of the second of | becnecked | Kemarks |
| 1. | Pavement | and the manager | | acourage du |
| a) | Road Junction condition | | | √S/U |
| b) | Condition of Surfacing | | | √\$/U |
| c) | Riding Quality | | | ✓ S/U |
| d) | Road Camber | | | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2 | Cross Drainag | e Line and | Substitution of the second | and a feet of the bill. |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3. | Road Furnitur | | P. Control of the Con | |
| | stones/Pavemen | t road markings are p | cautionary Board/km & 200m provided and maintained | Yes/No |
| | Compliance Hi | story | | and the second |
| a) | Status of ATR's | & any others | | NO |

Overall Rating

| Satisfactory (S) | S |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Agay Kumar Cys

DESIGNATION: EE 2 WD M ascurbi