

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: East Champaran	
Division : Arreraj		Length (km): 7.00	
Name of the Road: Guwahatiya to Kalaraya Path (part-B)			
Scheme/Programme: MAINTENANCE		Road Id No.: 31708300817	
Package No.:		Ongoing/Completed/Under Maintenance	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		Parameters to be checked	
Sl. No.			Remarks
1.	Pavement		S S/U
a)	Road Junction condition		S S/U
b)	Condition of Surfacing		S S/U
c)	Riding Quality		S S/U
d)	Road Camber		S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		No Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes Yes/No
g)	Compaction of flank/slope & raincuts if any		No Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		N/AS/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S S/SRI/U
c)	Condition of railings/slab/approach for Bridges		N/AS/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 02/12/2020