FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020 District: PATNA	
	APUR Length (km): 0.650	
	vishanpur FLOD Rd to Bilita Saraudh	a pmasy
Scheme/Programme		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance	- 100 (100
Sl. No.	Parameters to be checked	Remarks
l. Pavement		
a) Road Junction condition		SID
b) Condition	b) Condition of Surfacing	
c) Riding Qua	Riding Quality	
d) Road Cam	d) Road Camber	
Whether	e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
	(CC P	
g) Compaction of flank/slope & raincuts if any		Yes/No
2. Cross Dra	The second of th	
ALL ARTHUR DATE TO THE COMME	a) Condition of head walls in Hume pipe culverts including its painting	
b) Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
	Condition of railings/slab/approach for Bridges	
3. Road Fur	Depth of the control	
THE RESERVE OF THE PARTY OF THE	ign boards/informatory/cautionary Board/km & 200m ement road markings are provided and maintained	Yes/No
4 Complian	e i History	
a) Status of A	TR's & any others	

Overall Rating

S Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Anil Kumat DESIGNATION: J.E Bihta