FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020		District: Gaya	
Division: Gaya		Length (km): 5.16 KM	
Name of the Road: G	aya WEZITA	en Path To Mangrowen	
Scheme/Programme:	MAINTENANCE	anj Path To Mangrawan_ 3054 (Old)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	√S/U	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No b	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_S/SRI/Ui	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

G. M. Frotony (S)	
Satisfactory (S) Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

DE 2.12.20 (Signature)

NAME: Charety Shelder Kunner

DESIGNATION: TE