

# FIELD INSPECTION REPORT

|                        |                                              |              |          |
|------------------------|----------------------------------------------|--------------|----------|
| Date of Inspection :   | 3.12.20                                      | District:    | Patna    |
| Division :             | Masaurhi                                     | Length (km): | 1.025 KM |
| Name of the Road:      | SPM Road to Mo? addin pur                    |              |          |
| Scheme/Programme:      | MAINTENANCE                                  | Old.         |          |
| Package No.:           |                                              | Road Id No.: |          |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓        |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance ✓ |              |          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | ✓ S/U    |
| b)      | Condition of Surfacing                                                                                               | S/U ✓    |
| c)      | Riding Quality                                                                                                       | S/U ✓    |
| d)      | Road Camber                                                                                                          | ✓ S/U    |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         | NO       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                          |   |

Factories are situated on this road. Heavy vehicles are plying. This road needs upgradation.

(Signature)

NAME: Ajay Kumar Singh  
DESIGNATION: EE RWD Masaurhi