FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		**District:** Buxar	
Division : R.W.D. Dumraon		**Length (km):** 4.50 KM	
Name of the Road: NH30 to Rewatiya se Sonosar.			
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2/12/2020

2/12/2020
AE

2/12/20

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		**District:** Buxar	
Division : R.W.D. Dumraon		**Length (km):** 3.40 KM	
Name of the Road: Sakrauli lakri to Kharwasiya road			
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2/12/2020 TE, Nawanagar

2/12/2020 AE

2/12/2

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	**District:** Buxar
Division : R-W-D. Dumraon	**Length (km):** 9.66 KM
Name of the Road: Sikraul Lakshto Kuransaraipur via Bhadar Athar Road	
Scheme/Programme: MAINTENANCE ✓	
Package No.:	**Road Id No.:**
Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2/12/2020 JE, Nawanagar

2/12/2020 AE

2/12/20 EE

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		**District:** Buxar.	
Division : R.W.D. Dumraon		**Length (km):** 1.80 KM	
Name of the Road: Nawanagar Thakurwasi PWD road to Bhatauli via Rampur			
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2/12/2020 JE, Nawanagar

2/12/2020 AE

2/12/20 DE

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		**District:** Buxar	
Division : R.W.D. Dumraon.		**Length (km):** 3.10 KM	
Name of the Road: Repair of road from Nawanagar to Kukurbhukka.			
Scheme/Programme:	MAINTENANCE		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance.	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Maintenence.	

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

2/12/2020 JE, Nawanagar

2/12/2020 AE

2/12/20 EE

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		**District:** Buxar	
Division : R.W.D. Dumraon		**Length (km):** 1.90 KM	
Name of the Road: NH30 Km 1 to Lokpur.			
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

2/12/2020

2/12/2020 AE

2/12/20 EE

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection : 2.12.2020	**District:** Buxar
Division : R.W.D. Dumraon	**Length (km):** 16.19 KM
Name of the Road: NH-30 Paroogadih to Sarirg via Bhatauli Kesath PSTB.	
Scheme/Programme: MAINTENANCE ✓	
Package No.:	**Road Id No.:**
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	**Compliance History**	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

2/12/2020 AE

2/12/20 EE

(Signature)

NAME: