

# FIELD INSPECTION REPORT

Date of Inspection: 02.12.20	District: Duxar
Division: Duxar	Length (km): 4.40 km
Name of the Road: Nya Shandi - Bhavathar to Kaneli giri	
Scheme/Programme: MAINTENANCE	
Package No.: AR-2 / Duxar / 01 / 2018	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) X	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

N.K. Himanshu

(Signature)

DESIGNATION:

सहायक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, राजपुर

सहायक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, राजपुर

Scanned with CamScanner

Scanned with CamScanner

Scanned with CamScanner