

FIELD INSPECTION REPORT

Date of Inspection :	02/12/20	District:	Jehanabad
Division :	Jehanabad	Length (km):	2.20 Km
Name of the Road: Repair ab Road from Bandhuganj - Sukiyawan Road (Lalsahiya) to Biglipur.			
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/N
b)	Condition of Surfacing	✓ S/N
c)	Riding Quality	✓ S/N
d)	Road Camber	✓ S/N
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

Arjun Kumar
02/12/20 02/12/2020
(Signature)

NAME: Narender Kumar Chandel
DESIGNATION: AE J.E
ARJUN KUMAR