

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020.	District: Gaya.
Division : RWD Imangang	Length (km): 11.25
Name of the Road: Pakardih to Shikaliya via Kneibar Path	
Scheme/Programme:	MAINTENANCE Maintenance
Package No.: —	Road Id No.: 10502400811
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'U'
b)	Condition of Surfacing	S/U 'U'
c)	Riding Quality	S/U 'U'
d)	Road Camber	S/U 'U'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 'Y'
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 'Y'
g)	Compaction of flank/slope & raincuts if any	Yes/No 'N'
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 'U'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U 'S'
c)	Condition of railings/slab/approach for Bridges	S/SRI/U 'U'
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No 'No'
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	'U'

2.12.20.
(Signature) AE

NAME: Niaz kumar Singh
AE RWD Imangang.