

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020.		District: Gaya.	
Division : RWD Imanganj		Length (km):	6.60.
Name of the Road: Naiga to Mandar Path			
Scheme/Programme:		MAINTENANCE	
Package No.:		—	
Road Id No.:		10502400810	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'S'
b)	Condition of Surfacing	S/U 'S'
c)	Riding Quality	S/U 'S'
d)	Road Camber	S/U 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 'No'
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 'Yes'
g)	Compaction of flank/slope & raincuts if any	Yes/No 'yes'
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U —
c)	Condition of railings/slab/approach for Bridges	S/SRI/U —
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No 'Yes'
4.	Compliance History	
a)	Status of ATR's & any others	ATR

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Subendrakumar
2/12/20
(Signature) ~~BE~~ J.E.

NAME: Subendrakumar
J.E, R.W.D, Imanganj