

FIELD INSPECTION REPORT

Date of Inspection :	3-12-2020	District:	Buxar
Division :	Buxar	Length (km):	6.640 km
Name of the Road:	Buxar - Sasaram road to Katariya		
Theme/Programme:	MAINTENANCE	MR 13054 New policy 2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance

No.	Parameters to be checked	Remarks
Pavement		
1)	Road Junction condition	✓ S/U
2)	Condition of Surfacing	✓ S/U
3)	Riding Quality	✓ S/U
4)	Road Camber	✓ S/U
5)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
6)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
7)	Compaction of flank/slope & raincuts if any	✓ Yes/No
Cross Drainage		
8)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
9)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
10)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
11)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
Compliance History		
12)	Status of ATR's & any others	NO

Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Atk Hussain Ansari

Hussain
3-12-2020
(Signature)
J-5

R.W.D. WORKS Section
Rajpur