FIELD INSPECTION REPORT

Date of	Inspection: 2	-12-2020	District: Craya	
Division	n: Tikani		Length (km): 1.701m	- Superior Control Con
Name o	f the Road: Be	la barasar roas	d to kai i fatehland do	a ulatfo nv
	/Programme:	MAINTENANCE	To HILL No.	
Package		1 Characterist	Road Id No.: ad/Under Maintenance	
	of the Project: a case of:	Naw Connectivity/	Up gradation/ Maintenance	subministration and a subministration of the
	a case or:	Parameters to		Remarks
Sl. No.		Parameters to	O DE CHECKEG	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√s/U
d)	Road Camber			√s/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			sed – Yes/No
f)	Contraction Joints provided or not (CC Pavement)			- Yes/No
g)	Compaction of flank/slope & raincuts if any			♥Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			ing - S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			- S/SRI/U
c)	Condition of railings/slab/approach for Bridges			- S/SRI/U
3.	Road Furnitu	re		
a)	Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained			00m Yes/No
4.	Compliance H	listory		
a)	Status of ATR's & any others			
11 Y				Operation of the second of the
Overall Rating :		Satisfactory (S)		S
		Satisfactory but	requires Improvement (\$R	
		Unsatisfactory (U)	- 1

NAME:

Scanned with Cam

(Signature) A. G. B. Caby RWD WIDW Tay-n.